

Better Chemistry. Better Business.

Hubbard-Hall Inc.



Operating and Trouble Shooting of Hot Black Oxide Baths for Steel Alloys

By Scott Papst Technical Service Director October 9, 2009



Better Chemistry. Better Business.

What is Black Oxide?

Mild Steel

- Black oxide process converts metallic iron surface Fe⁰ to Fe₃O₄
 (magnetite) by controlled oxidation.
- Fe₃O₄ is a complex of FeO (ferrous oxide) and Fe₂O₃
 (ferric oxide).
- Red Rust is Fe₂O₃



Better Chemistry. Better Business.

What is Black Oxide (cont.)?

Stainless Steel

- Magnetite
- CrO₂ chromium dioxide black
- CrOH₃-H₂O chromic hydroxide (black)
- Ni oxide
- Sulfides of Fe, Ni, and Cr



Better Chemistry. Better Business.

Why Black Oxide?

- Attractive black finish
- Increased corrosion resistance
- No dimensional change
- Lubricating qualities
- Economy and ease of application



Better Chemistry. Better Business.

Functional uses of Black Oxide:

- Absorbent base of rust preventives
- Reduced coefficient of friction
- Adhesion promoter for organic coatings
- Improved bonding of rubber
- Reduced eye fatigue anti reflective
- Light and heat absorption
- Anti-galling properties
- Metal forming after blackening



Better Chemistry. Better Business.

Typical Process for Steel and Stainless Steel

- Alkaline Clean
- 2. Rinse
- 3. Acid Pickle (activate):
 - a) Mild Steel only when scale, rust or oxides are present.
 - b) Stainless Steel all alloys, 2-7 minutes.
- 4. Blacken:
 - a) Mild Steel @285°F. rolling boil
 - b) Stainless Steel @255°F. rolling boil
- 5. Rinse
- 6. Sealer



Better Chemistry. Better Business.

Typical Blackening Times

Mild Steel Stainless Steel

Low carbon: 10 min. Need contact with mild steel

High carbon: 10-15 min. 300 series: 5-7 min. max

Tool steel: 30-60 min. 400 series: 2-5 min. max

Examples: A-3, H11,S7, etc. pH 17-4: 2-5 min. max

Heat Treated Steel: 15-20 min. Ductile and cast iron: 2-7 min.



Better Chemistry. Better Business.

Base Metal Effect of Mild Steel

- Rust: Must be removed. Rust in equals rust out
- Scale: Must be removed
- Surface smut: De-smut prior to blackening
- Matte Finish: Results in a matte black
- Polishes Finish: Bright shiny black
- Heat Treated: Scale common, prone to smutting
- <u>Induction Hardened:</u> May produce off-color results. Require longer activation and blackening times
- <u>Tools Steel:</u> Usually require extended blackening times



Better Chemistry. Better Business.

Trouble Shooting Hot Black Oxide for Mild Steel

<u>Problem</u>

Loose, red oxide that wipes off

- Transfer time too long
- Rectifier needed (too much coloidal iron present)
- Temperature too high
- Solution dries on



Better Chemistry. Better Business.

Trouble Shooting Hot Black Oxide for Mild Steel

Problem

Red iron oxide that does not wipe off

- Transfer too long
- Temperature too high
- Heat treat scale present
- High silica alloy (>3%)
- High Carbon Alloy (>1%)



Better Chemistry. Better Business.

Trouble Shooting Hot Black Oxide for Mild Steel

Problem

Red cast/ back ground

- Galvanic problems
- High chrome alloy
- Need longer immersion time
- Temperature too high



Better Chemistry. Better Business.

Trouble Shooting Hot Black Oxide for Mild Steel

Problem

Green cast / brown

- Temperature too low
- Add salts
- Increase temperature at boil
- Rust present prior to black



Better Chemistry. Better Business.

Trouble Shooting Hot Black Oxide for Mild Steel

Problem

Blotchy black uncoated areas

- Poor cleaning
- Nesting
- Transfer time too long
- Increase part agitation
- Improve cleaning



Better Chemistry. Better Business.

Trouble Shooting Hot Black Oxide for Mild Steel

Problem

Smutty black (rubs off)

- Carbon on surface
- Tool steel alloy
- Too long of an acid pickle
- Return to cleaner to desmut



Better Chemistry. Better Business.

Trouble Shooting Hot Black Oxide for Mild Steel

Problem

No blackening

- Chrome contamination
- Oxidizers depleted
- Loss of boil
- High surface area



Better Chemistry. Better Business.

Base Metal Effect on Stainless Steel

200 and 300 Series
 Non magnetic; 3-5 minute activation

required. 5-7 minutes blackening.

Blackens best in contact with mild steel.

• 302 and 303 Alloys Sometimes require special activation step.

• 309 and 310 Alloys Requires 3-hour activation.

400 Series and PH Series
 Magnetic; May require pre-passivation.

2-7 minutes activation. 5-7 minutes

blackening.



Better Chemistry. Better Business.

Trouble Shooting Hot Black Oxide for Stainless Steel

Problem

No blackening

- Contact with mild steel
- Surface not activated
- Increase pickle time
- Surface oxides requires passivation
- Bath damaged by overheating



Better Chemistry. Better Business.

Trouble Shooting Hot Black Oxide for Stainless Steel

Problem

Smutty black

- Too much pickle time
- Over activation
- Bath requires skimming
- Bath need desludging
- Parts need passivation
- Temperature to high



Better Chemistry. Better Business.

Trouble Shooting Hot Black Oxide for Stainless Steel

Problem

Iridescent colors

- Temperature too low
- Temperature too high
- Needs contact with mild steel
- Bath damage by overheating



Better Chemistry. Better Business.

Trouble Shooting Hot Black Oxide for Stainless Steel

Problem

Blotchy and uncoated

- Poor cleaning
- Nesting
- Need Contact with mild steel
- Poor surface finish
- Increase agitation
- Improve cleaning