



Product Bulletin

Better Chemistry. **Better Business.**

Hallcoat A 1

Product Code: 2420005
Revised Date: 03/26/2007

Hallcoat A 1

Hallcoat A 1 is a water soluble powdered-chromated product used for applying a chemical conversion coating (iridescent-gold color), by immersion, on aluminum and aluminum alloys to provide paint adhesion or corrosion protection. The coating is applied from the solution at room temperature and produces a film which can be used as a final finish or can be dyed various colors.

Hallcoat A 1 will produce a coating that will meet the requirements of Mil-C-5541 E Class 1A, although it is not presently on the QPL list.

OPERATING CYCLE

1. Soak clean in either etch or non etch cleaner.
 - (a) soak clean in non-etch cleaner 187 ne, 8 oz/gal (45 to 60 gms/l), 160 - 180f, (71-82c) 1 - 5 minutes.
 - (b) soak clean in extend etch, 4 - 10 oz/gal (30 to 75 gms/l) 120 - 160f (48-72c) 30 seconds to 3 minutes.
2. Cold water rinse.
3. Deoxidize/desmut in either of the non-chromate deoxidizer/desmutters.
 - (a) deoxidizer 13l, 20 to 30% (vol) room temperature, 1 - 5 minutes.
 - (b) deoxidizer 13, 8-12 oz/gal (60 to 90 gms/l), room temperature. 1-5 minutes.
4. Cold water rinse.
5. **Hallcoat A 1** (see conditions below).
6. Cold water rinse.
7. Dye.
8. Cold water rinse.
9. Hot water rinse, 140f, 2-5 seconds (temperature never above 160f).
10. Dry.

EQUIPMENT

Polyethylene, koroseal or equivalent lined tank.



Better Chemistry. **Better Business.**

Hallcoat A 1

Product Code: 2420005
Revised Date: 03/26/2007

SOLUTION MAKEUP AND OPERATING CONDITIONS

Hallcoat A 1 concentration range-----3/4 - 2 1/4 oz/gal (5.6 to 16.8 gms/l)
Temperature-----70 - 90f (21-32c)
Immersion time (1 1/4 oz/gal)-----30 seconds - 5 minutes.
Ph range-----1.1 - 1.9
Ph range (1 1/4 oz/gal)-----1.3 - 1.6

MAINTENANCE & CONTROL OF HALLCOAT A 1 SOLUTION

1. Pipette a 10 ml sample into a 500 ml erlenmeyer flask, add 250 mls of distilled water.
2. Add 10 mls of 10% potassium iodide.
3. Add 5 mls of conc sulfuric acid.
4. Immediately titrate with 0.1 n sodium thiosulfate until the solution turns straw color. Add 1 ml of 1% starch solution and continue titrating until the blue solution changes to clear green.

Titration X 0.08 = Oz/Gal (Analyzed)

Additions: $(1.25 \text{ oz/gal} - (\text{oz/gal analyzed}) \times \frac{\text{gls sol}}{16}) = \text{lbs to be added to tank.}$

Ph meter is preferred to ph paper for determining ph. The ph may be lowered by additions of 42 be' nitric acid (3 fl oz/100 gallons will lower ph by 0.1). Caustic soda may be used to raise the ph.

WASTE DISPOSAL

Neutralize solutions of before discharging the **Hallcoat A 1** solution. It will be necessary to reduce the hexavalent chrome with either the addition of: sodium meta sulfite, sodium bisulfite, sodium sulfite or sodium hydrosulfite.

After the hexavalent chrome has been reduced, then adjust the ph of the solution between to a ph between 6 to 8 with either soda ash or caustic soda. The function of the alkaline addition is to neutralize the acidic **Hallcoat A 1** solution and to precipitate out the metallic hydroxides.



Product Bulletin

Better Chemistry. **Better Business.**

Hallcoat A 1

Product Code: 2420005
Revised Date: 03/26/2007

CAUTION

Hallcoat A 1 is a chromate-fluoride acidic product. Avoid contact with skin and eyes. Wear protective clothing, goggles and rubber gloves. Flush exposed areas immediately with clean, cold water. In case of injury, contact a doctor immediately.

WARRANTY

THE QUALITY OF THIS PRODUCT IS GUARANTEED ON SHIPMENT FROM OUR PLANT. IF THE USE RECOMMENDATIONS ARE FOLLOWED, DESIRED RESULTS WILL BE OBTAINED. SINCE THE USE OF OUR PRODUCTS IS BEYOND OUR CONTROL, NO GUARANTEE EXPRESSED OR IMPLIED IS MADE AS TO THE EFFECTS OF SUCH USE, OR THE RESULTS TO BE OBTAINED.